

Lot #	Description	Mileage or Hours	Serial No.	Notes
1	2008 Chevrolet Impala	133,054	2G1WD5E35C1326652	
2	2008 Ford Ranger	133,791	1FTZR15E08PA96366	Rust repair
3	2012 Ford Flat Bed Truck	115,703	1FDBF3A64CEA16524	
3	2016 Addco truck mounted message board		900486	
4	2014 Ford F-350	102,225	1FDBF3A63EEA43278	
4	2016 Addco 001-10848 Message Board		900485	
5	2011 Ford Ranger	106,643	1FTKR1EE5BPA14219	Cooling system repair/head gasket
6	2012 Ford F-150	155,161	1FTFX1EF1CKD98580	Transmission repair
7	2012 Ford F-150	227,696	1FTFX1EF5CKD98579	4 wheel drive repair, check engine light on
8	2013 Chevrolet Impala	158,044	2G1WD5E3XD1254431	Check engine light on/misfire, rear bumper impact absorber rust
9	2011 Chevrolet Impala	151,582	2G1WD5EM1B1281345	
10	2016 Ford PI Explorer	196,716	1FM5K8AR7GGD05987	
11	2008 Ford F-350 Single Axle Dump	73,002	1FDWF36528EE36372	Body damage, rust repair
12	2009 Ford F-350 Single Axle Dump	67,034	3FMTK1S50RMA11723	Rust repair
13	2011 Ford F-350 Single Axle Dump	91,807	3FMTK1S50RMA11723	Body damage, rust repair

14	2008 OMJC Portable Signal - Trailer Mounted	N/A	1223PU2008	
15	2007 OMJC Portable Signal - Trailer Mounted	N/A	1200PU2007	
16	2007 OMJC Portable Signal - Trailer Mounted	N/A	1199PU2007	
17	2007 OMJC Portable Signal - Trailer Mounted	N/A	1207PU2007	
18	2010 John Deere 6330 Tractor	3,911	L06330H641054	
18	2010 Diamond DSF60C Side Flail Mower		5655	
19	1996 John Deere 5300 Tractor	3,620	LV5300E630044	
20	2017 Bobcat 3650 Utility Vehicle	1,877	B3C317107	
20	2017 Bobcat 70" ABUTV Bucket Attachment		B1CZ00620	
20	2016 Bobcat 62" GPBUTV Bucket Attachment		860GG	
21	2014 Kubota Zero Turn Mower	2,638	20057	
22	2015 John Deere Outfront Mower	1,815	1TC1580VCGR020016	
23	2000 Polaris Magnum 350 4-Wheeler	4,450	4XACD32A8YB405281	Needs engine
24	1993 Woods Rotary Mower		2953	

25	2009 SnowEx SP-8500H Salt Spreader		None	Frame is very rusty, missing parts, no spreader chute or motor
26	2014 Toro FP-3000 Compactor		313000322	
27	2003 Western Snow Plow		2002013	
28	2017 Kubota RTV1100C	1,849	19222	Engine & Transmission repair
29	2019 Ford PI Explorer	71,961	1FM5K8AR3KGB54719	Severe damage; total loss - SALVAGE TITLE
30	2011 Ford F-350 Single Axle Dump	89,555	1FDRF3G67BEA86006	Rust repair
31	2011 Ford F-350 Single Axle Dump	48,253	1FDRF3G62BEA86009	Rust repair
32	2009 Ford F-350 with Flat Bed	88,023	1FTWF31529EB25912	Check engine light on, fuel system repair
32	2009 Fisher 7 1/2 ft Snow Plow		None	
32	2009 SnowEx SP-8500H Salt Spreader		None	Frame is rusty, hydraulic repair
33	2009 Ford F-350	134,371	1FTWF31509EB25911	Rust repair
33	2009 Fisher Snow Plow		None	
33	2009 SnowEx Salt Spreader		None	Frame is rusty
34	Coats 1400 2D Wheel Balancer		1705300998	220 Volts